


D- Montageanleitung

GB- Assembly instructions

F- Instructions de montage

PL- Instrukcja montażu

RU- Инструкция по монтажу

NL- Montagehandleiding

TR- Montaj talimatı

RO- Instrucțiuni de montaj

IT- Istruzioni per il montaggio

SK- Návod na montáž

CZ- Návod k montáži

HU- Szerelési útmutató

BG- Ръководство за монтаж

P- Instruções de montagem

ES- Instrucciones de montaje

SRB- Uputstvo za montažu

SLO- Navodila za vgradnjo





HR- Upute za montažu










LT- Montavimo instrukcija













LV- Montāžas instrukcija


EST- Montaažijuhend



S- Monteringsanvisning






A  x24	B  Ø8,L-30 x26	C  Ø15,h12 x24	E  Ø3.5,L-16 x8
G  x13	I  x4	J K  x4 =  J +  K H 11.5mm	
L  Ø4,L-16 x16	M  Ø4,5,L-50 x3	N  Ø7,h1.5 x4	O  white Ø20,h1 x10
P  black Ø20,h1 x6	T  x8	Q  Ø3,L-20 x12	U  Ø7,L50 x4
V  SW4 x1	Z  SOFT CLOSE 433.03.123 x1	W  PUSH TO OPEN 433.03.523 x1	






Nr.		Menge	L x B x H (mm)
1	1/2	1x	1618 x 419 x 16
2	2/2	1 x	364 x 436 x 16
3	2/2	1 x	364 x 436 x 16
4	1/2	1 x	1618 x 431x 16
5	1/2	1 x	312 x 410 x 16
6	1/2	1 x	312 x 410 x 16
7	1/2	1 x	1618 x 150 x 16
8	1/2	1x	542 x 328x 3.2
9	1/2	1 x	548 x 328x 3.2
10	1/2	1 x	542 x 328x 3.2
11	2/2	1 x	525x 400 x 16
12	2/2	1 x	525 x 400 x 16
13	2/2	2 x	350 x 100 x 16
14	2/2	2 x	350x100 x 16
15	2/2	2 x	492 x 84 x 16
16	2/2	2 x	502 x 358 x 3.2
17	2/2	1 x	546 x 180 x 16
18	2/2	1 x	546 x 180 x 16
19	2/2	1 x	364 x 546 x 16
20	2/2	1 x	364 x 546 x 16










1






2







A		x12
C	 Ø15,h12	x8
B	 Ø8,L-30	x8
K		x4














9




I		x4
M	 Ø4,5,L-50	x3
Q	 Ø3,L-20	x4
G		x13



10




A		x4
B	 Ø8,L-30	x4
C	 Ø15,h12	x2





x2

11







U		x2
V		x1





x2

12


 $X1 = X2$


13




Q




Ø3,L-20

x8




x2

14



J



x4

N



Ø7,H 1.5




x4

E




Ø3.5,L-16

x8





15 **SOFT CLOSE
(GELB)**

PUSH TO OPEN




Z		L350	x1
W		L350	x1
L		Ø4,L-16	x8






16 **SOFT CLOSE
(GELB)**





PUSH TO OPEN






Z		L350	x1
W		L350	x1
L		Ø4,L-16	x8










20

O	white 	Ø20,H 1	x14
P	black 	Ø20,H 1	x6



21

