






Art. Nr. 2004 0947




LKZ 41164



- | | |
|----------------------------------|------------------------------|
| (D) Montageanleitung | (GB) Assembly instructions |
| (FR) Notice de montage | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montażu |
| (CZ) Montážní návod | (SK) Návod na montáž |
| (HU) Szerelési útmutató | (RO) Instrucțiuni de montaj |
| (TR) Montaj talimatı | (RU) Инструкция по монтажу |





A  7x32 x30	B  15x16 x4	C  15x10 x26	D  8x35 x26	E  4x50 x12	F  x4
G  M6x12 x8	H  4x16 x34	I  20x0.5 x4	J  7x50 x16	K  x12	L  3.5x13 x24
M  x4	N  M4x22 x4	O  4x30 x2	P  70x50 x2	Q  x2	R  x2
S  L150 x1	T  4x60 x2				




N	Size/MaB (mm)	Qty	✓	N	Size/MaB (mm)	Qty	✓
1	1548x68x38	1		9	706x180x12	2	
2	1504x60x16	1		10	706x180x12	2	
3	1502x925x38	1		11	693x158x12	2	
4	1502x447x22	1		12	2005x80x35	1	
5	400x250x16	2		13	1900x48x35	2	
6	2020x210x22	2		14	100x80x35	1	
7	1612x250x16	2		15	1578x698x12	2	
8	1568x180x12	2					

Service - Dienstverlening - Serwis - Servis - Сервисная служба




Name - Naam - Nazwa - Isim - Название

Nr. - No. - Номер



Typ - Type - Tip - Тип








1 x2








2 x2




3



4




5




H	4x16
	x6
R	
	x2
S	L150
	x1
T	4x60
	x2

 $L1=L2$




6 x2






B	15x16
	x4



7 x2





8 x2




9 x2

C 15x10
x18




10 x2



J 7x50
x12



11 x2



12 x2



13 x2

J 7x50 x4

K x12

L 3.5x13 x24

8

15

10

0, 14, 770, 770, 0

Diagram illustrating the assembly of the bed base. The main view shows the base board (10) being attached to the frame using casters (K) and screws (L). The dimensions 770 and 770 are indicated for the base board segments. The inset shows the installation of the casters (K) onto the base board (10) using screws (L). The inset also shows the installation of the casters (K) onto the frame using screws (L). The inset shows the installation of the casters (K) onto the frame using screws (L).

J		7x50	x4
K			x12
L		3.5x13	x24

K  **x12**

L  **3.5x13**
x24

14

P 70x50 x1

Q x1

1

3

5

5

P







Q

P




P  70x50
x1




Q  **x1**

15



16 x2





G		M6x12	x4
H		4x16	x2
O		4x30	x2

