


Montageanleitung Assembly instruction Instructions de montage Instrucciones de montaje Istruzioni per il montaggio Руководство по монтажу Instrukcja montażu Montážní návod Návod na montáž Szerelési utasítás Инструкция за монтаж Kurulum Talimatları Navodilo za montažo Montagehandleiding A s e n n u s o h j e Upute o montaži Instrucțiuni de montaj Monteringsveiledning

إرشادات التركيب


Monteringsvejledning Instruções de montagem Monteringsanvisning

Beschläge / fittings / Ferrures pour meubles / Herrajes / Guarnizioni / Крепления / Okucia / Kování / Kovanie / Vasalások / обков / Parçaları / okovje / Hang- en sluitwerk / helat / Oblo-ge / armături, balamale / Beslag / بعض التركيبات / Beslag / Guarnições / Beslag





Sie benötigen:
You need:
Vous avez besoin de:
Necesita:
Le servono :
Вам потребуются:
Potrebujete:
Tarvitset:
Aveți nevoie de :
Du behøver:
سوف تحتاج إلى:



Potrzebne są:
Potřebujete:
Potrebujete:
Szőkséges eszközök:
На Вас са Ви нужни:
Ihtiyaciniz:
U hebt nodig:
Trebate:
Du skal bruge:
Necessita de:
Du behöver:



BRISTOL 1000 Art.-Nr. 4020-1000



Teile / article / Pièces / Piezas / Pezzi / части / Części / Díly / Diely / Alkatrészek / Детали / parçalar / dele / Onderdelen / osat / Dijelovi
piese / Deler / والتجهيزات / Dele / Peças / Delar




B

4,0x30
4 x SR 3

2 x GR34


ZB1

1




2

2x




3

2x




4

2x






5


2x




C





1







2






3




D







1




2




E




1





2




3




F




1



2



3



G

1 x GR34


4,0x30
2 x SR 3

2 x TB14


2 x TB13

3,5x15
4 x SP1


1 2x




2 2x




3




H


- 

1 x GR34
- 



4,0x30
2 x SR 3
- 

2 x TB9
- 


3,5x15
4 x SP1






I



1




2




180°


J



1





2




K

6 x AK1


1



2



3



L

3,5x15
8 x SP1

7,0x50
4 x VB3



W2




2x

1

2



3




M







50 x SO3


3,5x30
10 x SP 11



5 x
GL1




N









1



2



O



P






- 3,5x15



4 x SP1
- M4x8



4 x SG1



R

6 x AK3

