




Oregon






- | | |
|----------------------------------|---------------------------------------|
| D Montageanleitung | GB Assembly instructions |
| FR Notice de montage | NL Handleiding voor de montage |
| CZ Montážní návod | IT Istruzioni di montaggio |
| RO Instrucțiuni de montaj | RU инструкция по сборке |
| PL Instrukcja montażu | SK Návod na montáž |
| HU Szerelési útmutató | TR Montaj talimatı |



Service • Assistenza • Dienstverlening • Serwis Servis • Szerviz • Сервисная служба


| | |
|---|-----------------|
| Name • Nom • Nome • Naam Nazwa • Jméno • Názov • Név Denumire • Ísim • Название | Orgon EB |
| Nr. • No. • N° • Номер • Č • Sz | SH50 |
| Typ • Type • Tip • Típus • Tipo Тип | BS G |







| A | B | C | D | E | F |
|----|---------|----|---------|---------|-------|
| | | | | | |
| 4x | 8x 8x40 | 2x | 2x 8x50 | 4x 8x60 | 4x M8 |



| | | |
|---|--|---------|
| A | | 4x |
| B | | 4x 8x40 |
| C | | 2x |
| D | | 2x 8x50 |





| | | | | | |
|---|---|---------|---------|-------|---|
| E |  | 4x 8x60 | 4x 8x40 | 4x M8 | <p>Achtung! Schrauben nicht überdrehen</p> <p>FR Attention! Ne serrez pas trop</p> <p>CZ Dávej Pozor! Nepřetahujte</p> <p>RO Ai Grija! Nu strângeți</p> <p>PL Uwaga! Nie dokręcać zbyt mocno</p> <p>HU Vigyázz! Ne húzza túl</p> <p>GB Watch Out! Do not over tighten</p> <p>NL Let Op! Niet te vast</p> <p>IT Attento! Non stringere</p> <p>RU Осторожно! Не затягивайте</p> <p>SK Dávaj Pozor! Nepretahujte</p> <p>TR Dikkat! Üzerinde sıkmayın</p> |
| F |  | 4x M8 | 4x 8x40 | 4x M8 | |
| B |  | 4x 8x40 | 4x 8x40 | 4x M8 | |
| E |  | 4x 8x60 | 4x 8x40 | 4x M8 | |

