




# WESTMANN

## MONTAGEANLEITUNG

Westmann Metall Hochbeet

„Primus XL“ • WMHPS772010(-WG)




















**BEI FRAGEN, KONTAKTIEREN SIE  
UNSEREN KUNDENSERVICE:**

50NRTH GmbH  
Straßburgstraße 14-16  
D-54516 Wittlich

service@50NRTH.com  
+49 (0) 6571 95117-0


## BAUTEILE:




Ax6 	(1) (2)	Bx6 	(1) (2)	Cx6 	(1) (2)	Dx2 	(1) (2)
Ex2 	(3)	Fx2 	(3)	Gx2 	(3)	Hx2 	(3)
Ix2 	(3)	Qx84 	(3)	Ux4 	(3)	Vx4 	(3)
Wx4 	(3)	Xx84 	(3)	Yx6 	(3)	Zx1 	(3)
		M4					
		M4*14					

## MONTAGEANLEITUNG:


1 x 6




2 x 2




3 × 2




4




**5** × 2




**6**



7



8



9

