

MORRIS JUBI
8141/2300
2100/8142

D MONTAGEANLEITUNG
BEDIENUNGSANLEITUNG

NL HANDLEIDING VOOR DE MONTAGE
GEBRUIKSAANWIJZING

TR MONTAJ TALIMATI
KULLANIM KLAVUZU

RO INSTRUCȚIUNI DE INSTALARE
INSTRUCȚIUNI DE UTILIZARE

FR NOTICE DE MONTAGE
MANUEL 'INSTRUCTIONS

HU KÖZGYŰLÉS UTASÍTÁSOK
KEZELÉSI UTASÍTÁS

SI NAVODILA ZA MONTAŽO
NAVODILA ZA UPORABO

ES INSTRUCCIONES DE MONTAJE
MANUAL DEL USUARIO

GB ASSEMBLY INSTRUCTIONS
INSTRUCTION MANUAL

PL INSTRUKCJA MONTAŻU
INSTRUKCJA OBSŁUGI

RU ИНСТРУКЦИЯ ПО МОНТАЖУ
ИНСТРУКЦИЯ ПО ЭКСПЛУАТАЦИИ

IT ISTRUZIONI DI MONTAGGIO
MANUALE DI ISTRUZIONI

SK MONTÁŽNY NÁVOD
NÁVOD NA POUŽITIE


CZ MONTÁŽNÍ NÁVOD
NÁVOD K POUŽITÍ

PT INSTRUÇÕES DE MONTAGEM
MANUAL DO USUÁRIO



HR UPUTE ZA MONTAŽU
UPUTE ZA UPOTREBU

F/B


240510






0019




0019





0090










L











R







g H-120  X2	v H-120  X1	i L-4  X1	s H-120  s ₁ X3	q M6*25 [mm]  X12
---	---	---	---	---





g H-120  X2	i L-4  X1	s H-120  s ₁ X2	q M6*25  X8
---	---	--	--








0019










g H-120

 X4












v H-120

 X1



i L-4

 X1

s H-120

 X5









q M6*25

 X20









0019



Name · Naam · Nazwa · Ísim · Название · Nume · Nome · Názov · Názov ·
 Název · Neve




MORRIS JUBI






Typ · Type · Tip · Тип · Tipo · Típus



L

R



g H-120 	v H-120 	s H-120  s ₁ 	q M6*25 [mm] 
--	--	---	--

