



A1		x43	A2) x34	A3		x34
A4		x18	A5		x6 Ø3,5x16	A6	(F)	x12
A7		x4 Ø2,5x15	A8	0	x12	A9		x2
A10		x4 M4x25	A11		x2	A12	1xL DD	1xR
A13	2xL	2xR	A14		х4			





- D Sehr geehrter Kunde,hier haben Sie die Möglichkeit mitgelieferte Schrauben nachzumessen.
- (UK) Dear customer. Here you have the possiblility of measuring the supplied screws.
- (FR) Cher client, Ici vous avez la possibilité de mesurer les vis livrees.
- NL Zeer geachte cliënt, hier heeft U die mogelijkheid meegeleverde schroeven na te meten.
- T Gentile cliente, qui avete la possibilità rimisurare viti in dotazione.
- (RU) Уважаемый клиент, здесь у вас есть возможность измерить входящих в комплект винтов.





Teil Nr.	Anzahl	Kasten Nr.	Maß, mm	
Pieces Nr.	Quantity	Colli Nr.	Dimensions, mm	
Pièces Nr.	Quantité	Colli Nr.	Dimensions, mm	
Stukken Nr.	Hoeveelheid	Colli Nr.	Afmetingen, mm	'
Pezzi Nr.	Quantità	Colli Nr.	Dimensioni, mm	
Часть Ном.	Количество	Коробка Ном.	Размеры, mm	
1	1	A	1000x355x39	
2	1	В	841x354x39	
3	1	C	841x354x39	
4	1	D	921x180x16	
5	1	Е	917x364x16	
6	1	F	845x98x16	
7	1	G	845x116x16	
8	1	Н	318x100x16	
9	1	I	302x116x25	
10	1	J	302x116x25	
11	1	K	703x34x34	
12	1	L	703x34x34	
13	2	M	410x94x16	
14	2	N	300x71x16	
15	2	О	300x71x16	
16	2	P	356x71x16	
17	2	S	292x364x3	
	l			


















































- Dübel und Schrauben für die Wandbefestigung müssen in Korrespondenz mit der Beschaffenheit der Wände vor Ort ausgewählt werden.
- Wall plugs and screws for the wallmountning must be selected in correspondence with the condition of the walls locally.
- (FR) Pour la fixation murale veuillez utiliser des vis et chevilles adaptées à votre type de mur.
- NL De keuze van schroeven en deuvels ter bevestiging aan de muur is afhankleijk van het type muur.
- Tasselli e viti per il montaggio a parete devono essere selezionati a seconda del tipo di parete.
- (RU) Винты и дюбеля для монтажа на стене, выбрать, в зависимости от типа стены.

Important - Please read these instructions fully before starting assembly

Check you have all the components and tools.

Remove all fittings from the plastic bags and separate them into their groups.

Keep children and animals away from the work area, small parts could choke if swallowed.

Make sure you have enough space to layout the parts before starting.

Do not stand or put weight on the product, this Assemble on a soft level surface to avoid could cause damage.

Assemble the item as close to its final position (in the same room) as possible. Do not place furniture directly in front of radiators, fires or any other source of heat.



Parts of the assembly will be easier with 2 people.

damaging the unit or your floor.



We do not recommend the use of power drill/drivers for inserting screws, as this could

damage the unit. Only use hand screwdrivers.

Dispose of all packaging carefully and responsibly.

General care and maintenance

Only clean using a damp cloth and mild detergent, do no use bleach or abrasive cleaners.

From time to time check that there are no loose screws and connectors on this unit.

This product should not be discarded with household waste. Take to your local authority waste disposal centre.

Cleaning and care of high gloss surfaces

Regular dusting with a dry cloth will keep your units clean.

Do not clean with products contaiing the following: Acetone, (e.g nail varnish remover). Ammonia (e.g.bleach). or Sodium hydroxide (e.g. Caustic soda, drain and oven cleaners).

Clean marks with a damp cloth.

Do not use abrasive cleaners.

In the event of accidental contact with aggresive cleaners, rinse thoroughly with water.

Do not allow spillages to stay on the surface for long.

To remove stubborn stains, wipe over with a damp cloth and washing up liquid.

Use place mats to protect the surface from moisture and heat.

Maximum weight limit

