






Luise





1



2



3




2/2

1	1x	1/2
2	2x	2/2
3	1x	2/2

A	M6*12	B	M6*40	C	M6*12	D	Ø18*Ø6*1.5	E	4mm
	9X		9X		4X		9X		1X
F	6mm								
	1X								

I.

1.



A



M6*12

9X

F




6mm

1X



2.



C



M6*12

4X

E




4mm

1X





11.

3.






B	M6*40 9X
D	Ø18*Ø6*1.5 9X
E	4mm 1X
100%	





4.



Séparez les éléments avant de trier



Luise L



1	1x	2/3
2	1x	3/3
3	1x	1/3
4	1x	1/3
5	2x	2/3
5	2x	3/3
6	2x	2/3
6	2x	3/3




3/3

A	M8*35 24X	B	M8*18 12X	C	M8*40 4X	D	Ø18*Ø8*1.5 40X	E	5mm 1X
F	2X								


I.

1.



A	M8*35 8X
D	Ø18*Ø8*1.5 8X
E	5mm 1X
100%	


2.



A	M8*35 8X
D	Ø18*Ø8*1.5 8X
E	5mm 1X
100%	

II.

3.




B M8*18
4X


D Ø18*Ø8*1.5
4X

E 5mm
1X

F
2X



4.



B M8*18
8X



D Ø18*Ø8*1.5
8X

E 5mm
1X



III.

5.



C


M8*40
4X

D



Ø18*Ø8*1.5
4X

E

5mm
1X



6.



A


M8*35
8X

D


Ø18*Ø8*1.5
8X

E

5mm
1X



7.



E

5mm
1X






LE TRI
+ FACILE




Séparez les éléments avant de trier


Luise



1



2




1	1X
2	1X



1/1

A

M6*20



4X

B

Ø18*Ø6.5*1.5



4X

C


4mm



1X

I.

1.



A


M6*20
4X

B


Ø18*Ø6.5*1.5
4X

C

4mm
1X



2.



C

4mm
1X



Séparez les éléments avant de trier