








# Tanja T





1	1x
2	1x
3	2x
4	2x



AA	7x50 8x	B	8x30 4x	C	8x30 16x	D	4x	E	4x	F	4x
G	D=15mm 8x	H	1x								

I.



1.





2.



3.





4.







II.

5.




6.




# TANJA

# LEB / REB


LEB




REB





NW  
13



LEB



REB



		
1	1x	2/2
2	1x	2/2
3	1x	1/2
4	1x	1/2
5	3x	2/2

**A** 9x  
  
M8 L-80

**B** 3x  
  
M8


**C** 21x  
  
Ø8

**D** 9x  
  
M8 L-100

**E** 3x  
  
Ø8

I.


1.



A	3x
	
M8 L-80	
B	3x
	
M8	
C	6x
	
Ø8	
E	3x
	
Ø8	


2.

3x





II.

3.





D	9x
	
M8 L-100	
C	9x
	
Ø8	

4.





III.

5.








6.






A	6x
	M8 L-80
C	5x
	Ø8

IV.

7.






# Tanja



1

2

3



1	1x
2	1x
3	1x

A	M6x20	B	M6x12	C	Ø18xØ6x1.5	D	4MM	E	M4x25	F	
	4x		4x		4x		1x		4x		2x

**I.**

**1**

E M4x25  
4x

F  
2x

100%

**2**

B M6x12  
4x

D 4MM  
1x

75%

**3**

A M6x20  
4x

C Ø18xØ6x1.5  
4x

D 4MM  
1x

75%

**4**

D 4MM  
1x

75%

