



Art. No. 64103941, 68424449, 76606562, 93619828, 23841745, 54063707, 27195159, 31732217, 65770461, 89431812, 17231724, 60952925, 57312811, 71441631, 18936247, 38439960, 41755127, 69444918, 46745964, 75738959

GOLDPOINT

bedsofa chaiselong



- | | | | |
|-------------|------------------------------------|-------------|--------------------------------|
| (D) | Montageanleitung | (GB) | Assembly instructions |
| (FR) | Notice de montage | (IT) | Istruzioni di montaggio |
| (NL) | Handleiding voor de montage | (PL) | Instrukcja montażu |
| (CZ) | Montážní návod | (SK) | Návod na montáž |
| (HU) | Szerelési útmutató | (RO) | Instrucțiuni de montaj |
| (TR) | Montaj talimatı | (RU) | Инструкция по монтажу |



LKZ 40937










**Service • Usługa • Обслуживание • Servizio • Un service
Serviciu • Služba • Servis • Szolgáltatás**


Name • Nom • Nome • Naam
• Nazwa • Název • Názov
• Név • Nume • Isim
• Название




GOLDPOINT

• Nr • No • N° • Номер • C • Sz

64103941, 68424449, 76606562, 93619828, 23841745, 54063707, 27195159, 31732217,
65770461, 89431812, 17231724, 60952925, 57312811, 71441631, 18936247, 38439960,
41755127, 69444918, 46745964, 75738959







3

